

Pre-Shipment Inspection Report

No.: A0000007 **Date:** November 11, 2008 **Supplier:** 天全企業
P/O No.: S974668A **Customer Item No.:** QQQ
Description: 山水仙, 薑花, 金魚草, 太
S/C No.: S974668 **Our Item No.:** 000000046
Customer No.: 00002 **Customer Order No.:** Cust. Order No. 1
Quantity: 60 pc **Sample Size:** 5 pc



Acceptable Quality Level (AQL):		Critical	Major	Minor
		<div></div>	0	0
Inspection	Details	Critical	Major	Minor
01. Product				
Item dimensions 產品尺寸	10.00x10.00x10.00 cm	<div></div>		0
03. Inner Pack				
Inner 內盒數量	6.0 pc/set	<div></div>		0
Inner dimensions 內盒尺寸	10.00x10.00x10.00 cm	<div></div>		1
04. Master Pack				
Outer 每箱數量	12.0 pc/box	<div></div>		2
Outer dimensions 外箱尺寸	13.00x30.00x30.00 pc	<div></div>		1
Case bar code 外箱條碼	AA8896	<div></div>		3
Outer cube 外箱材數	0.41 cu.ft.	<div></div>		4
Outer N.W.	5.50 kg	<div></div>		4
Outer N.W.	7.80 kg	<div></div>		8
Unit outer 數量單位	pc	<div></div>		7
Shipping marks	see below	<div></div>		0
Carton nos. 箱號	1-5	<div></div>		1
10. Functions				
General operations test x 一般功能測試	Function Test/一般功能測試. Per data sheet.	<div></div>		6

(continued)

Pre-Shipment Inspection Report

- 2 -

No. A0000007

November 11, 2008

Inspection	Details	Critical	Major	Minor
20. Documents				
	Operations manual			0
40. Surface Treatments				
	Surface scratches and more description till the 80th character.			0
Total Defects:		0	0	0

AQL Result:

None

Inspection Result:

None



Some comments for this image taken during inspection. Can be anything.
Max. 450 characters.


Nothing.



More comments about inspection or images.

Remarks: Say something about your effort. Arraise yourself if you think appropriate.

Shipping Marks:



天輪系統股份有限公司

Richard L. Chen